

referred to the State.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06

Site Name: Wood Protection Company		CERCLIS ID#	:TXD059345116	
Alias Site Names:				<u></u>
Address: 5151 S. Loop East				
City/County or Parish/State/Zip Code: Hou	ston, Harris, Texas	77033		
Report Type, Date, and Author: Preliminary A	ssessment (PA), Se	ptember 1997, R	loy F. Weston, Inc.	
RECOMMENDATION				
(X) 1. No Further Remedial Action Planned under Superfund (NFRAP)	() PA () SSI () ESI () Oti	() HR () RA () RI/I		() High () Medium () Low
() 3. Action Deferred to: () RCRA () NRC		performed by		VA G T T T T T T T T T T T T T T T T T T
NOTIFY AUTHORITY:				
() Removal () RCRA () Remedial () State () CERCLA Enforcement () Federal Facility SEND SSSR COPIES TO: (X) 6SF-AC	() TSCA () NPDES () UIC () 6WQ-SP	() CAA () NRC () SPCC () ATSDR	() SMCRA () Resource Trustee: () Other: (X) State Agency	() Other
SERE SOON COPIES TO: (A) COP-AC		()AIODN	(A) State Agency	() Oulei
DISCUSSION: The Wood Protection Company is an active wood Houston, Texas. The facility was owned by Po (PCP) was used to preserve wood products. To treated wood products with chlorinated copper discontinued that practice in the early 1990s.	entawood Life Vacu he property was pu	um Treated Com	pany from 1952 to 1972. I Protection Company in 197	Pentachlorophenol 2. The company
The waste sources associated with this site, in pressure treating cylinders and sumps, and drur stressed vegetation and a suspected release from	ns containing solid	and sludge waste		
A review of the Preliminary Assessment (PA) re release of wood treating contaminants to drinki site impacted the remaining Hazard Ranking Sys under potential to release conditions, will not go and then disposed of under small quantity gene	ng water wells have stem (HRS) migration enerate a significan	e not been docum on pathways. In	nented or have the past acti addition, there is a limited to	vities related to this arget population, that

Page 1 of 2, PA Report SSSR

A decision of "No Further Remedial Action Planned" (NFRAP) under Superfund will be entered in CERCLIS, and the site will be

Based upon currently available information, this site fails to meet the minimum criteria required to be included, or proposed, at this time on the NPL by the EPA. The NPL is EPA's list of sites that are priorities for further investigation and, if necessary, response action under CERCLA, 42 USC 960001, etseq. Other actions maybe appropriate under State Authorities.



89545

Cita	Name:	
oue:	WHITE I	

Wood Protection Company

CERCLIS ID #:

TXD059345116

APPROVALS:

Philip Ofosu Report Reviewed by:___

(Site Assessment Manager 6SF-RA)

Disposition Recommended by: Susan Webster

(Team Leader 6SF-RA)

Disposition Recommended by: Ragan Broyles

(Section Chief 6SF-RR)

Disposition Approved by: Charles A. Gazda (Branch Chief 6SF-R)

Signature:

Signature: KNOW

Date: